Date:	7/15/2016			
			s. The City of Milwaukee, the Redevelopme	
			te, or for omissions through error or oversigh leral Block Grant or HOME programs.	nt. The list does not necessarily include
Exterior	Condition Report			
Location Site	Required Work Landscaping	n/a ☑ Yes 🗆	Note/Comments Self Help	Cost \$
Site	Steps/Handrails	n/a ☑ Yes □	GON THEIP	\$
	Service walks	n/a □ Yes ☑		\$ 1,500.0
	Fencing	n/a ☑ Yes □		\$
	Parking	n/a ☑ Yes □		\$
	Retaining walls	n/a ☑ Yes □		\$
	Other	n/a ☐ Yes ☑	tree removal	\$ 2,000.0
	Other	n/a ☐ Yes ☑	parking slab - pave	\$ 2,500.0
Garage	Singles: repair	n/a □ Yes □		\$
	Shingles: Roof over existing	n/a □ Yes □		\$
	Shingles:Tear off & re-roof	n/a ☐ Yes ☐		\$
	Gutters/downspouts	n/a ☐ Yes ☐		\$
	Flashing	n/a ☐ Yes ☐		\$
	Eaves	n/a ☐ Yes ☐		\$
	Siding	n/a ☐ Yes ☐		\$
	Doors	n/a ☐ Yes ☐		\$
	Windows	n/a ☐ Yes ☐		\$
	Slab	n/a ☐ Yes ☐		\$
	Paint	n/a ☐ Yes ☐		\$
	Electrical	n/a ☐ Yes ☐		\$
	Other	n/a ☐ Yes ☐		\$
Porches	Roof	n/a ☑ Yes □		\$
	Deck-upper	n/a ☑ Yes □		\$
	Decklower	n/a ☑ Yes 🗆		\$
	Steps/handrails	n/a ☑ Yes 🗆		\$
	Ceiling	n/a ☑ Yes 🗆		\$
	Guardrails	n/a ☑ Yes 🗆		\$
	Structural	n/a ☑ Yes □		\$
	Paint	n/a ☑ Yes □		\$
	Other	n/a □ Yes □		\$

Other□

Scope of Work for Property Located at: 5915-17 North 65th Street

Property is: Single Family □ Duplex ☑

## House

Chimney	n/a ☑	Yes □		\$
Shingles: repair	n/a _☑	Yes 🗆		\$
Shingles: Roof over existing	n/a ☑	Yes 🗆		\$
Shingles:Tear off & re-roof	n/a □	Yes ☑		\$ 6,500.00
Gutters/downspouts	n/a □	Yes ✓	_	\$ 1,000.00
Flashing	n/a ☑	Yes 🗆		\$
Eaves	n/a ☑	Yes □		\$
Siding	n/a □	Yes ☑		\$ 7,500.00
Storm Doors	n/a ☑	Yes 🗆		\$
Prime ("main") Doors	n/a ☑	Yes □		\$
Storm Windows	n/a ☑	Yes □	_	\$
Prime ("main") Windows	n/a ☑	Yes 🗆	_	\$
Paint	n/a 🗆	Yes ☑	all trim and windos	\$ 2,500.00
Foundation	n/a ☑	Yes 🗆		\$
Electrical	n/a □	Yes ☑	exterior fixtures	\$ 450.00
Other	n/a 🗆	Yes ☑	repair rotted trim around house	\$ 1,000.00
Other	n/a □	Yes □		\$
Other	n/a □	Yes □		\$
Other	n/a □	Yes 🗆		\$

Exterior: Estimated Cost:\* \$ 24,950.00

\*average contracted cost. Actual costs may vary. Self help will reduce the amount.

interior Co	onaition Report								
	Unit: Entire unit (single family)	_				Lower unit of duplex	✓		
Mechanical	Upper unit of duplex Required Work					Other			
Heating									
	Repair/replace boiler	n/a	<b>✓</b>	Yes		_			\$
	Repair radiation	n/a	<b>V</b>	Yes					\$
	Repair/replace furnace	n/a	<b>V</b>	Yes		_			\$
	Repair ductwork	n/a	<b>V</b>	Yes		_			\$
	Replace thermostat	n/a	<b>V</b>	Yes					\$
	Repair/replace grilles	n/a	<b>V</b>	Yes		_			\$
Flootvicel	Tune boiler/furn. insp ht exchang	j€n/a		Yes	<b>V</b>				\$ 3,300.00
Electrical	Repair/replace receptacles	n/a		Yes	<b>V</b>	_		_	\$ 150.00
	Repair/replace switches	n/a		Yes	<b>V</b>				\$ 150.00
	Repair/replace fixtures	n/a	V	Yes					\$
	Install outlets and circuits	n/a		Yes	<b>V</b>				\$ 1,000.00
	Install outlets and circuits	n/a	<b>V</b>	Yes		_			\$
	Install outlets and circuits	n/a	<b>V</b>	Yes					\$
	Install outlets and circuits	n/a	<b>V</b>	Yes					\$
	Upgrade service	n/a		Yes	<b>V</b>				\$ 950.00
	Other	n/a		Yes					\$
	Other	n/a		Yes		_			\$
Plumbing	Repair/replace kitchen sink	n/a	V	Yes		_			\$
	Repair/replace kitchen sink fauce	ein/a	V	Yes					\$
	Repair/replace tub	n/a	<b>V</b>	Yes		_			\$
	Repair/replace tub faucet	n/a		Yes	<b>V</b>				\$ 450.00
	Repair/replace toilet	n/a	<b>V</b>	Yes					\$
	Repair/replace lavatory	n/a	<b>V</b>	Yes					\$
	Repair/replace lavatory faucet	n/a	<b>V</b>	Yes					\$
	Repair/replace wash tub	n/a	<b>V</b>	Yes					\$
	Repair/replace wash tub faucet	n/a	<b>V</b>	Yes					\$
	Unclog piping:	n/a	<b>V</b>	Yes					\$
	Repair drain/waste/vent piping	n/a		Yes	<b>V</b>				\$ 500.00
	Repair water piping	n/a		Yes	<b>V</b>				\$ 1,000.00
	Repair/replace water heater	n/a		Yes	V				\$ 750.00
	Other	n/a		Yes	<b>V</b>	LAUNDRY TRAY			\$ 400.00
	Other	n/a		Yes					\$

Windows	Replace broken glass	n/a [	] Yes	V		\$ 100.00
	Repair or replace sash	n/a 🕓	Z Yes			\$
Doors	Repair or replace doors	n/a [	] Yes	V		\$ 150.00
	Repair or repl. locks/latches	n/a 🗔	∑ Yes		Self Help	\$
Valls/Ceilin	gs Repair or repl. @ defective	n/a [	] Yes	<b>V</b>		\$ 200.00
Paint	Repair or repl. @ defective	n/a √	ກ Yes	П		\$
Fire Safety						
	Install smoke/CO alarm:bsmt.	n/a [	] Yes	<b>V</b>	Self Help	\$ 50.00
	Install smoke/CO alarm: 1st flr.	n/a [	] Yes	<b>V</b>	Self Help	\$ 50.00
	Install smoke/CO alarm: 2nd flr.	n/a 🖸	☑ Yes		Self Help	\$
Handrails	Repair/replace defective	n/a 🗔	∕ Yes		Self Help	\$ 
Stairs	Repair defective	n/a [	☑ Yes			\$
Floors	Repair defective	n/a [	] Yes	<b>V</b>	<u></u>	\$ 1,500.00
Other		n/a [	] Yes	V	REAR INTERIOR DOOR	\$ 250.00
		n/a [	] Yes			\$
	-	n/a [	] Yes		_	\$
		n/a [	∃ Yes			\$

	ondition Report Unit: Entire unit (single family) Upper unit of duplex Required Work					Lower unit of duplex Other	<b>⊒</b>		
Heating	•	- 1-	_	<b>V</b>	_			•	
	Repair/replace boiler	n/a	V	Yes				\$	
	Repair radiation	n/a	<b>✓</b>	Yes				\$	
	Repair/replace furnace	n/a	<b>✓</b>	Yes				\$	
	Repair ductwork	n/a	<b>V</b>	Yes		_		\$	
	Replace thermostat	n/a	V	Yes				\$	
	Repair/replace grilles	n/a	V	Yes				\$	
=1	Tune boiler/furn. insp ht exchang	j∈n/a	V	Yes				\$	
Electrical	Repair/replace receptacles	n/a		Yes	V			\$	150.00
	Repair/replace switches	n/a		Yes	<b>V</b>	_		\$	150.00
	Repair/replace fixtures	n/a	V	Yes				\$	
	Install outlets and circuits	n/a		Yes	<b>V</b>			\$	1,000.00
	Install outlets and circuits	n/a	V	Yes				\$	
	Install outlets and circuits	n/a	<b>V</b>	Yes				\$	
	Install outlets and circuits	n/a	V	Yes				\$	
	Upgrade service	n/a		Yes	V			\$	950.00
	Other	n/a		Yes				\$	
	Other	n/a		Yes				\$	
Plumbing	Repair/replace kitchen sink	n/a	V	Yes				\$	
	Repair/replace kitchen sink fauce	ein/a	V	Yes		_		\$	
	Repair/replace tub	n/a		Yes	<b>V</b>	TUB AND FAUCET		\$	750.00
	Repair/replace tub faucet	n/a	V	Yes				\$	
	Repair/replace toilet	n/a	V	Yes				\$	
	Repair/replace lavatory	n/a	V	Yes				\$	
	Repair/replace lavatory faucet	n/a	V	Yes				\$	
	Repair/replace wash tub	n/a	V	Yes				\$	
	Repair/replace wash tub faucet	n/a	V	Yes				\$	
	Unclog piping:	n/a	V	Yes				\$	
	Repair drain/waste/vent piping	n/a		Yes	V			\$	500.00
	Repair water piping	n/a		Yes	V			\$	1,000.00
	Repair/replace water heater	n/a		Yes	V			\$	750.00
	Other	n/a		Yes	$ \mathbf{\nabla}$	LAUNDRY TRAY		\$	1,000.00

\$

n/a □ Yes □

Other

Windows						
	Replace broken glass	n/a □	Yes ☑		\$	100.00
	Repair or replace sash	n/a ☑	Yes 🗆		\$	
Doors	Repair or replace doors	n/a _☑	Yes 🗆	_	\$	
	Repair or repl. locks/latches	n/a ☑	Yes □	Self Help	\$	
Walls/Ceiling					*	
	Repair or repl. @ defective	n/a □	Yes ☑		\$	1,000.00
Paint	Repair or repl. @ defective	n/a ☑	Yes □		\$	
Fire Oafate	- ropan or ropin & donoctive	1,00			Ψ	
Fire Safety	Install smoke/CO alarm:bsmt.	n/a ☑	Yes 🗆	Self Help	\$	
	Install smoke/CO alarm: 1st flr.	n/a ☑	Yes 🗆	Self Help	\$	
	Install smoke/CO alarm: 2nd flr.	n/a □	Yes ☑	Self Help	\$	50.00
Handrails	Repair/replace defective	n/a 🔽	Yes □	Self Help	\$	
Stairs				•		
Floors	Repair defective	n/a ☑	Yes 🗌		\$	
rioors	Repair defective	n/a □	Yes 🔽		\$	1,000.00
Other	riopan dolocaro	.,,			Ψ	.,000.00
		n/a □	Yes □		\$	
		n/a 🔲	Yes 🗆		\$	
		n/a 🔲	Yes 🗆		\$	
		n/a □	Yes 🗆		\$	
				Interior: Estimated Cost:	\$	19,350.00
				Total Exterior and Interior Cost:*	\$	44,300.00
					•	,

Inspected by: Andy Yeager Date: 7/15/16

## **Self Help**

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

## **Important Information Regarding Permits**

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located at 7630 W. Mill Road.

 $<sup>\</sup>ensuremath{^*}\text{average}$  contracted cost. Actual costs may vary. Self help will reduce the amount.